


# WT-1640 Diamond Core Drill 4560W



WATSON POWER TOOLS

## 1640 Core Cutter 355mm

S.no	Part Name	QTY		S.no	Part Name	QTY
1	Water seal 40*58*8	2		36	Pad M35	2
2	Water circle 250	1		37	Flat Rolling Needle 35	2
3	Faucet 200-PT	1		38	Bearing 6201	2
4	Top wire M46(one word)	1		39	F gear lever 250	1
5	Main axxs 230 tune	1		40	Volume 512	1
6	Flesh flat pad 200A	2		41	Pad 250.	1
7	Separation film 200A	2		42	Dialing knob 250	1
8	Spindle gear 2300-6	1		43	Bearing 6201	1
9	Curved bullet pad 2004	5		44	Rotor OB-255C	1
10	Ring 250	1		45	Bearing 6200	1
11	Nut 200A	1		46	Bend 200	1
12	Roller bearings BAM1212	1		47	Hegonal screw M580	2
13	Inner card 52	1		48	Pad M5	2
14	Bearing 3206	1		49	Pad M5	2
15	Gear box 250.	1		50	Stator OB-255C	1
16	Hegonal screw M6110	4		51	Gum shell 200	1
17	Pad M6	4		52	Stator shell 250	1
18	Pad M6	4		53	Parameter 8180531	1
19	Plece 250	1		54	Hegonal screw M410	2
20	Cylinder 9.5*35	1		55	Round Cross Saew M4 12	2
21	Volume 415	1		56	Cross level screw M4*10	1
22	Class I tooth shaft 2300-2	1		57	Brush the nest 200	2
23	Marketing 4*10	1		58	Carbon Brush 8186	2
24	Class I gear 250-1(10)	1		59	Round Cross Screw M4*8	2
25	Bearing 6201	2		60	Brush frame 200	2
26	Middle cover 250	1		61	Swich Box Cover 200-PT	1
27	Oring 31.5*1.8	1		62	Cross level saew MM 10	1
28	Pulling spring 855	2		63	Cross tapping screw M16	2
29	Iron ring p 10*35	2		64	Threading board 200	1
30	Type II high-speed gear 2300-5	1		65	Power cord 3*10*35M	1
31	Ring 250	1		66	Cross level screw MM 20	2
32	Class II tooth shaft 230C-4	1		67	Cross kevel screw M4*10	1
33	Rolling pin pad M40	2		68	Switch Box 200-PT	1
34	Flat Rolling Needle p 40	2		69	Switch D18	1
35	Type II low-speed gear 2300-3	1				