




WATSON
INDUSTRIAL

3112 ANGLE GRINDER 1200W INDUSTRIAL



WATSON POWERTOOLS

3112 Angle Grinder 1200w Industrial

S.No.	Part No.	Spare Part Name	Qty	S.No.	Part No.	Spare Part Name	Qty
1	3112-001	inner flange	1	28	3112-028	middle cover	1
2	3112-002	cutting disc	1	29	3112-029	rotor	1
3	3112-003	outer flange	1	30	3112-030	dustproof ring	1
4	3112-004	wheel guard	1	31	3112-031	spacer 17xq7.1x0.3	1
5	3112-005	dustproof cover	1	32	3112-032	bearing 607	1
6	3112-006	output shaft	1	33	3112-033	bearing sleeve	1
7	3112-007	screw M5x13	4	34	3112-034	windshield	1
8	3112-008	front cover	1	35	3112-035	rubber column	2
9	3112-009	O ring 0.75x45.4	1	36	3112-036	stator	1
10	3112-010	wool ring	1	37	3112-037	housing	1
11	3112-011	bearing 6001	1	38	3112-038	screw ST4x12	2
12	3112-012	bearing cover	1	39	3112-039	side cover	2
13	3112-013	screw M4x10	3	40	3112-040	screw ST3x7.5	4
14	3112-014	big gear	1	41	3112-041	brush holder	2
15	3112-015	needle bearing HK0709	1	42	3112-042	carbon brush	2
16	3112-016	selflock pin	1	43	3112-043	coil spring	2
17	3112-017	screw ST4x25	4	44	3112-044	insulating plate	2
18	3112-018	screw M4x10	1	45	3112-045	connecting plastic	1
19	3112-019	screw M4x20	1	46	3112-046	screw ST4x16	4
20	3112-020	selflock cap	1	47	3112-047	cable clamp	1
21	3112-021	selflock spring	1	48	3112-048	cable protector	1
22	3112-022	gear box	1	49	3112-049	switch	1
23	3112-023	side handle	1	50	3112-050	electric capacity	1
24	3112-024	nut M6	1	51	3112-051	cable	1
25	3112-025	pinion	1	52	3112-052	rear cover	1
26	3112-026	spacer 19.2xq7.1x0.2	1	53	3112-053	spanner	