




3140 ANGLE GRINDER 1450W(B.S) INDUSTRIAL



WATSON POWERTOOLS

| 3140 Angle Grinder 1450w Industrial | | | |
|--|-----------------|--------------------------|------------|
| S.NO | PART NO. | SPARE PART NAME | QTY |
| 1 | 3140-001 | Upper inflang | 1 |
| 2 | 3140-002 | Down inflang | 1 |
| 3 | 3140-003 | Disc cover | 1 |
| 4 | 3140-004 | screw M4x16 | 4 |
| 5 | 3140-005 | dustproof cover | 1 |
| 6 | 3140-006 | shaft | 1 |
| 7 | 3140-007 | front cover | 1 |
| 8 | 3140-008 | O ring | 1 |
| 9 | 3140-009 | 6201 bearing | 1 |
| 10 | 3140-010 | circlip for hole | 1 |
| 11 | 3140-011 | gear | 1 |
| 12 | 3140-012 | Needle bearing HK0810 | 1 |
| 13 | 3140-013 | gear box | 1 |
| 14 | 3140-014 | screw ST4X25 | 4 |
| 15 | 3140-015 | shelf lock pin cap | 1 |
| 16 | 3140-016 | spring | 1 |
| 17 | 3140-017 | O ring 6*4*1 | 1 |
| 18 | 3140-018 | self lock pin | 1 |
| 19 | 3140-019 | nut M6 | 1 |
| 20 | 3140-020 | pinion | 1 |
| 21 | 3140-021 | spacer ©19.2X07.1X0.2 | 1 |
| 22 | 3140-022 | bearing 629 | 1 |
| 23 | 3140-023 | spacer (20x9.1x0,2) | 1 |
| 24 | 3140-024 | ring 32x1 | 1 |
| 25 | 3140-025 | Middle plate | 1 |
| 26 | 3140-026 | armature | 1 |
| 27 | 3140-027 | dustproof ring | 1 |
| 28 | 3140-028 | spacer (\$18 x 08.2x0.5) | 1 |
| 29 | 3140-029 | bearing 608 | 1 |
| 30 | 3140-030 | bearing sleeve | 1 |
| 31 | 3140-031 | windshield | 1 |
| 32 | 3140-032 | Rubber | 2 |
| 33 | 3140-033 | stator | 1 |
| 34 | 3140-034 | screw ST3x7.5 | 4 |
| 35 | 3140-035 | carbon brush | 2 |
| 36 | 3140-036 | insulating sheet | 2 |
| 37 | 3140-037 | brush holder | 2 |
| 38 | 3140-038 | spring | 2 |
| 39 | 3140-039 | line bank | 1 |
| 40 | 3140-040 | housing | 1 |
| 41 | 3140-041 | switch | 1 |
| 42 | 3140-042 | capacitance | 1 |
| 43 | 3140-043 | line pressing plate | 1 |
| 44 | 3140-044 | screw ST4X14 | 4 |
| 45 | 3140-045 | rear cover | 1 |
| 46 | 3140-046 | side cover | 2 |
| 47 | 3140-047 | cable cover | 1 |
| 48 | 3140-048 | cable | 1 |
| 49 | 3140-049 | wrench | 1 |