





# 5150 ANGLE GRINDER 950W PRO (B.S)



WATSON POWERTOOLS

## 5150 Angle grinder 950 w (B.S)

S.NO	PART NO.	SPARE PART NAME	QTY
1	5150-001	outer flange	1
2	5150-002	Inner flange	1
3	5150-003	output spindle	1
4	5150-004	Dustproof cover	1
5	5150-005	Screw M4x14	4
6	5150-006	fore cover	1
7	5150-007	Bearing 6201	1
8	5150-008	Circlip for hole	1
9	5150-009	big gear	1
10	5150-010	Needle bearing HK0810	1
11	5150-011	crew St4.2x20f	4
12	5150-012	Gear box	1
13	5150-013	spindle lock pin	1
14	5150-014	spindle lock spring	1
15	5150-015	spindle lock button	1
16	5150-016	hex Nut M6	1
17	5150-017	pinion	1
18	5150-018	o type ring @22*02	1
19	5150-019	Bearing 608	1
20	5150-020	Bearing retaining plate	1
21	5150-021	Crew M4X8	2
22	5150-022	armature	1
23	5150-023	scraper seal	1
24	5150-024	bearing Pt607	1
25	5150-025	Bearing sleeve	1
26	5150-026	affle	1
27	5150-027	screw st3.5x75A	2
28	5150-028	stator	1
29	5150-029	Housing	1
30	5150-030	brush holder	2
31	5150-031	Carbon brush	2
32	5150-032	Coil spring	2
33	5150-033	Screw ST3x10f	4
34	5150-034	filter screen	2
35	5150-035	Switch	1
36	5150-036	o type connection	1
37	5150-037	type connection	2
38	5150-038	wiring	1
39	5150-039	back cover	1
40	5150-040	Screw ST4x14f	1
41	5150-041	cord clamp	1
42	5150-042	Screw ST4x14a	2
43	5150-043	cord sleeve	1
44	5150-044	power cord	1
45	5150-045	wheel guard	1
46	5150-046	side handle	1
47	5150-047	two feet spanner	1