




**WATSON**  
PROFESSIONAL

# 5461 CUT OFF MACHINE 355MM



**WATSON** **POWERTOOLS**

## 5461 14" CUT OFF MACHINE PARTS LIST

No.	Description of part	QTY			
			46	nut M10	1
1	cord sleeve	1	47	outer hex bolt M10*32	1
2	power cord	1	48	629-RS bearing	1
3	screw ST4*14A	2	49	gear	1
4	cord clamp	1	50	distance set	1
5	left/right handle	1	51	square key	1
6	switch	1	52	front cover	1
7	screw M5*45	6	53	retaining ring for hole	1
8	nut M5	2	54	6203-RS bearing	1
9	left and right sub handle nameplate cover	2	55	spindle	1
10	carrying handle	1	56	inner flange	2
11	screw M5*35	2	57	outer flange	2
12	screw M5*35	1	58	Single mesh grinding wheel	1
13	screw ST4*16F	10	59	small flange	1
14	motor housing	1	60	outer hex bolt M10*20	3
15	screw M4*10	1	61	active shield	1
16	brush cap	2	62	rubber seal	5
17	carbon brush	2	63	screw M5*10	2
18	brush holder	2	64	nut M5	2
19	extensin spring	2	65	spring column pin	1
20	insulating sheet	2	66	seat	1
21	rear cover	1	67	release nut	1
22	screw M4*12	7	68	lead screw assembly	1
23	screw M5*10	2	69	washer $\Phi 8 * \Phi 16 * 1.5$	1
24	upper guard	1	70	vise pin	1
25	screw M5*20	4	71	clamp fence	1
26	shock absorption washer	1	72	washer $\Phi 8 * \Phi 20 * 2$	1
27	upper arm	1	73	nut M8	1
28	6203 bearing	1	74	angle adjustment vise	1
29	bearing retaining plate	1	75	spark cover	1
30	stainless steel washer $\Phi 17$	1	76	outer hex bolt M10*130	1
31	baffle	1	77	steel pipe	1
32	armature	1	78	nut M6	1
33	stainless steel washer $\Phi 10$	1	79	spring washer $\Phi 6$	1
34	6200 bearing	1	80	inner hex screw M6*16*	1
35	stator	1	81	washer	1
36	cotter pin	2	82	spring washer $\Phi 8$	2
37	lock down pin	1	83	screw M8*18	2
38	rubber column	1	84	base	1
39	lock down knob	1	85	lock nut	1
40	screw M5*12	2	86	bowl type washer	2
41	self-locking pin pressure plate	1	87	screw M6*14	1
42	self-locking spring	1	88	rubber feet	4
43	self-locking pin	1	89	sponge mat	1
44	screw M5*75	2			
45	spring washer	2			