





5151 ANGLE GRINDER 950W PRO (B.S)



WATSON POWERTOOLS

5151 Angle Grinder 950w (S.S)

S.NO	Part No.	Spare Part Name	Qty	S.NO	Part No.	Spare Part Name	Qty
1	5151-001	Outer Flange	1	25	5151-025	Bearing Sleeve	1
2	5151-002	Inner Flange	1	26	5151-026	Baffle	1
3	5151-003	Output Spindle	1	27	5151-027	Screw St3.5X75A	2
4	5151-004	Dustproof Cover	1	28	5151-028	Stator	1
5	5151-005	Screw M4X14	4	29	5151-029	Housing	1
6	5151-006	Fore Cover	1	30	5151-030	Brush Holder	2
7	5151-007	Bearing 6201	1	31	5151-031	Carbon Brush	2
8	5151-008	Circlip For Hole	1	32	5151-032	Coil Spring	2
9	5151-009	Big Gear	1	33	5151-033	Screw St3X10F	4
10	5151-010	Needle Bearing Hk0810	1	34	5151-034	Filter Screen	2
11	5151-011	Crew St4.2X20F	4	35	5151-035	Switch	1
12	5151-012	Gear Box	1	36	5151-036	O Type Connection	1
13	5151-013	Spindle Lock Pin	1	37	5151-037	Type Connection Buckle	2
14	5151-014	Spindle Lock Spring	1	38	5151-038	Wiring Cap	1
15	5151-015	Spindle Lock Button	1	39	5151-039	Back Cover	1
16	5151-016	Hex Nut M6	1	40	5151-040	Screw St4X14F	1
17	5151-017	Pinion	1	41	5151-041	Cord Clamp	1
18	5151-018	O Type Ring @22*02	1	42	5151-042	Screw St4X14A	2
19	5151-019	Bearing 608	1	43	5151-043	Cord Sleeve	1
20	5151-020	Bearing Retaining Plate	1	44	5151-044	Power Cord	1
21	5151-021	Crew M4X8	2	45	5151-045	Wheel Guard	1
22	5151-022	Armature	1	46	5151-046	Side Handle	1
23	5151-023	Scraper Seal	1	47	5151-047	Two Feet Spanner	1
24	5151-024	Bearing Pt607	1				