




# 5250 MARBLE CUTTER 110MM ( CM4SA )



WATSON POWERTOOLS

**5250 Marble Cutter 110mm (CM4SA)**

<b>S.NO</b>	<b>PART NO.</b>	<b>SPARE PART NAME</b>	<b>QTY</b>
1	5250-001	Screw M4X10	1
2	5250-002	Gear Box Cover	1
3	5250-003	Screw M7X18	1
4	5250-004	Out flange	1
5	5250-005	Inner Flange	1
6	5250-006	Spindle	1
7	5250-007	Key 3X10	1
8	5250-008	Screw m5x25	2
9	5250-009	Dust Protect Cover White	1
10	5250-010	Bearing Seat	1
11	5250-011	Bearing 6201	1
12	5250-012	Waher 32	1
13	5250-013	Big gear	1
14	5250-014	Waher 12	1
15	5250-015	Bearing 626	1
16	5250-016	Gear Box	1
17	5250-017	Rubber Parts 588	1
18	5250-018	Pinion	1
19	5250-019	Bearing 629	1
20	5250-020	Waher 19*9*0.5	1
21	5250-021	Key 2.5X10	1
22	5250-022	Armature	1
23	5250-023	Screw ST5X6 60	2
24	5250-024	Bearing 608	1
25	5250-025	Waher 22*0.3	1
26	5250-026	Filed Coil	1
27	5250-027	Pin 6*32	1
28	5250-028	Base	1
29	5250-029	Waher 8.5*16*1.8	1
30	5250-030	Base Adjusment	1
31	5250-031	Screw 5/16'-14	1
32	5250-032	Waher 14	1
33	5250-033	Handle cover	1
34	5250-034	Switch Lock cap	1
35	5250-035	Switch	1
36	5250-036	Switch cover	1
37	5250-037	Housing	1
38	5250-038	Screw ST4X14	1
39	5250-039	Screw M5X40	3
40	5250-040	Name plate	3
41	5250-041	Brush Holder	1
42	5250-042	Carbon Brush	2
43	5250-043	Brush Holder Cover	2
44	5250-044	Cable clamp	2
45	5250-045	Screw ST4X14	1
46	5250-046	Cable sleeve	2
47	5250-047	Cable	1
48	5250-048	Wrench	2